

OPERATING INSTRUCTIONS

1. Feature:

1. 2 functional keys: C/F, MAX/MIN
2. Temperature display format switch ($^{\circ}\text{C}/^{\circ}\text{F}$)
3. Indoor temperature range: 0°C -- 50°C (32°F \sim 122°F)
4. Indoor humidity display 20-90%RH
5. Indoor max and min humidity records function.

2. Normal states

1. Click the "C/F" key to switch between $^{\circ}\text{C}/^{\circ}\text{F}$
2. Click the "MAX/MIN" key to check maximal and minimum humidity, "Max" \rightarrow "Min"
 \rightarrow clear

3. Power-On and reset

1. When Power-On and reset, LCD full display for 3 seconds \rightarrow "--.-" \rightarrow enter the normal state

Instrukcja obsługi

1. Charakterystyka:

1. Dwa przyciski funkcyjne: C/F, MAX/MIN
2. Przełącznik formatu wyświetlania temperatury ($^{\circ}\text{C}/^{\circ}\text{F}$)
3. Zasięg pomiaru temperatury pomieszczenia: 0°C - 50°C (32°F - 122°F)
4. Wyświetlanie wilgotności powietrza w pomieszczeniu: 20 – 90%RH
5. Funkcja pomiaru maksymalnej i minimalnej wilgotności powietrza w pomieszczeniu.

2. Standardowe procedury

1. Naciśnij przycisk „C/F”, by zmienić format wyświetlania temperatury z $^{\circ}\text{C}/^{\circ}\text{F}$.
2. Naciśnij przycisk „MAX/MIN”, by sprawdzić pomiar maksymalnej i minimalnej wilgotności powietrza, „Max” \rightarrow „Min” \rightarrow od nowa (clear)

3. Włączanie i resetowanie

1. Aby włączyć lub zresetować urządzenie należy naciskać wyświetlacz LCD przez 3 sekundy \rightarrow pojawi się "--.-", \rightarrow powrót do standardowego trybu działania.